


Cold Saw Rules & Safety

If you suspect a machine is not operating properly, contact mw-benchttop@mit.edu immediately! Cell: 954 806 0954

Sticker



Safety



Hazards



Class

2

Machine Specific Safety Equipment

- Safety Glasses
- Hair Ties (and further hair restraints advisable)

Hazards

- Blades are sharp and running at extremely high speed, presenting a serious **CUT HAZARD**
- Flying metal chips can cause **EYE INJURIES**
- Coolants may cause possible **SKIN IRRITATION**
- Small parts can be **THROWN** if not properly clamped
- Poorly secured stock can **FLING** out

Dos

- **Do** use a clamp or vise to properly secure stock
- **Do** support overhanging work and signpost if it presents a hazard
- **Do** ensure machine is off and at a complete stand still before making adjustments or before cleaning shaving accumulations
- **Do** immediately absorb any coolant spills

Don'ts

- **Don't** let fingers get too close to the saw blade
- **Don't** place, measure or remove work unless the saw is stopped
- **Don't** apply extra force to the saw blade
- **Don't** leave saw running unattended